

Approved Process Sources D1-4426

[Boeing Approved Process Sources - Home](#)

[Nadcap Accreditation](#)

[Notes & Exceptions](#)

[Revision Summary](#)

[User Instructions & Requirements](#)

[Approved Sources Flow Chart](#)

[Approved Processors](#)

[Geographic APL](#)

[Process Code Listing](#)

[Specification Index Listing](#)

[Limitation Index](#)

[Boeing Contacts](#)

[Authorized Distributors of Aircraft Bearings](#)

[Authorized Distributors of Designated Fasteners](#)

[Frequently Asked Questions](#)

Document D1-4426 - Processes for BE10039983

Detail Information for Processor Code number: BE10039983	
Supplier Name: DICKSON TESTING CO INC	
Address:	11126 Palmer Ave,
City/town:	South Gate
Province/state:	CA 90280-7492
Country:	UNITED STATES
Area:	CA
Contact Name:	Jeffrey Hart
Title:	Quality Manager
Phone:	323 527-7307
Fax:	
Boeing Contact Name:	Chuck Partridge
Boeing Contact Email:	chuck.partridge@boeing.com

* An acronym in the "Nadcap Commodity" column only indicates that [Nadcap accreditation may be required](#) for this Process Code. It does not provide any indication of this company's actual Nadcap accreditation status.

Process Code	*Nadcap Commodity	Limitation Codes	Doc Notes	Nomenclature	Specification Number
003	AQS	None	.	Boeing approved QMS as defined in D1-4426 Processor Requirements Sec 6.16.3	Quality System
801	MTL	None	None	Determination of Hydrogen in Titanium	ASTM-E-1447
802	MTL	None	None	Mechanical Testing - Metallic	Mech. Testing
803	MTL	None	None	Metallurgical Testing	Met. Testing
806	HT	None	...	Temper Inspection of Non-ferrous Alloys (Conductivity Method including BAC 5651)	BAC 5946
807	MTL	None	None	Fracture Toughness Testing	ASTM-E-399